Panasonic Cameras Cannot be Found Using an IP Camera Finder after 20 Minutes

Panasonic cameras stop responding to the IP camera finder after they have been powered up for 20 minutes. This applies to the finder in exacqVision Client and the Panasonic search software.

To find a camera that has been powered up for 20 minutes or more, restart the camera to reset the timer.

Created On: 12th February 2021 **KB Number:** KB-00604-604-210212

