## IP Camera Detection Fails If Using Multiple Addresses on Same Interface

## **Symptom:**

IP camera detection fails

## **Problem:**

If more than one IP address has been assigned to the same network interface on a Windows system exacqVision Server may fail to use correct IP address, thus camera detection fails. Linux is not known to be affected.

## **Solution:**

Option 1: Temporarily remove all but one IP address from the interface. Restart the server service and re-attempt discovery.

Option 2: Update exacqVision Server to version 9.4 or later.

**Created On:** 3<sup>rd</sup> February 2021 **KB Number:** KB-00084-84-210203

